









# Increasing the lifespan of your motor

# Increasing the lifespan of your motor

In mission critical industries such as pharmaceuticals or paper and pulp, a motor malfunction can translate to millions in lost profit. Looking after the bearings in your motor by improving power quality increases its lifespan and reduces maintenance related downtime.

Many modern motors, in variable speed applications, are fitted with a Variable Speed Drives (VSD) which use a frequency inverters with semiconductor devices. The switching techniques used generate high rates of change of voltage, which can have undesirable effects on the motor.

Both long cable runs between the frequency inverter and the motor and fast switching times can contribute to the premature failure of a motor as the result of bearing damage or insulation failure. Other unacceptable

earth currents can also occur.



The great majority of motors in industry contain bearings, which are the main supporting elements of the application. The most sophisticated bearings for specialised applications are very precise devices; their manufacture requires some of the highest standards of precision in industry. These bearings are costly to replace and their failure can result in an entire application suffering downtime.

phenomena such as power losses, high acoustic noise levels and parasitic

The bearings constrain relative motion and reduce friction between moving parts in the motor. The design of the bearing may, for example, provide for free linear movement of the moving part or for free rotation

" A REO Sinus Filter Plus ++ has been connected to the output terminals of the frequency inverter to reduce the commonmode disturbances that would otherwise cause premature bearing failure. " around a fixed axis; or, it may prevent a motion by controlling the vectors of normal forces that bear on the moving parts. Many bearings also facilitate the desired motion as much as possible, for instance by minimizing friction. Bearings are classified broadly according to the type of operation, the motions allowed, or to the directions of the loads applied to the parts.

## Electrical erosion

Bearings in electrical motors have been known to suffer from electrical erosion. Unfortunately, this can occur relatively quickly after the application becomes live – often merely a matter of months. As a result,

maintenance and condition monitoring teams need to keep a close eye on bearings performance.

Electrical erosion is very hard to spot, but it leads to bearing damage and subsequently premature bearing failure. The only way to detect electrical damage is to connect an oscilloscope and probe to the motor application. Initially, erosion manifests in the form of tiny craters; a process called fluting. At a more severe level, electrical corrosion can cause blackened grease representing the degradation of the lubricant around the bearings.

# Our value proposition

Working with you to develop innovative, energy efficient and EMC compliant solutions for your electrical power control and power quality problems. Providing technical expertise to deliver an enhanced return on investment through lower energy consumption, superior process efficiency and increased product life. The conventional solution is to fit a low-pass filter at the output terminals of the frequency inverter, which reduces the differential-mode interference to a smooth sinusoidal waveform with a ripple content of less than five percent. However, this type of filter is inadequate for applications where the reliability of the motor is of upmost importance and where replacing the motor would come at a very high cost.

The solution is to use a conventional differential mode and a common-mode output filter. This helps eliminate bearing damage, such as localised corrosion, caused by heat and pitting as a result of pulsing currents.

Other benefits of using this combined solution include noise reduction, diminished current losses, reduction of radiated interference from cables, and prevention of hazardous voltages and leakage currents.

## Sinus Filter Plus ++ in practice

REO UK has applied the above solution to protect the bearings of an underground pump motor which is used in a combined geothermal and solar panel heating system.

The problem here is that the cable running from the frequency inverter to the pump is very long and the water column provides a low impedance path back to ground. The resultant current pulsing through the motor bearings can create serious damage to the motor. Unfortunately, replacing or repairing the pump is a very costly project.

A REO Sinus Filter Plus ++ has been connected to the output terminals of the frequency inverter to reduce the common-mode disturbances that would otherwise cause premature bearing failure.

The high-frequency interference causes the metering equipment to give inaccurate measurements - a problem also corrected by fitting the REO Sinus Filter Plus ++.

In applications where several motors are connected in parallel to a single frequency drive, the Sinus Filter Plus ++ can also help.

Electrical erosion is the main cause of premature bearing failures. Preventive maintenance can alleviate the risk of machine downtime and the costs associated with it. REO's Sinus Filter Plus ++ can preserve the health of bearings and prolong the life of your electrical motor.


### **Technical information**

Static converters produce considerable asymmetrical disturbance in the clock frequency range (2 to 20 kHz). These frequencies affect adjacent plant components. The harmonics of these clock frequencies have an effect on the EMC performance of the system. Drive and standard EMC filters are generally only tested with short cable lengths. Longer cable runs add additional load to the filter resulting in non-compliance. The Sinus Filter Plus ++ can solve these problems by feeding the common mode interference back to the DC Bus.

## IMPORTANT!

### Minimum clock frequency 8 kHz.

The inverter charge is increased by the feedback into the DC link. Please ensure that the inverter is suitable!




# Sinusoidal filter ++ CNW 961


## **Description:**

The REO Sinusfilter Plus++ enables suppresses interference not only on line cables to the motor but also to earth conductors. The REO Sinusfilter Plus++ also feeds incurring bearing currents into the DC-link so that these may not cause any damage to the mechanical system.

REO Sinusfilter Plus++ is used in any kind of application which requires safe mechanical continuous power and reliability. Examples of such applications are: Water treatment – especially heat pumps.

- Conforming to: EN 61558-2-20
- Test voltage:L-L 1000 V, DC 1s L-PE 2500 V, DC 1s
- Rated voltage:  $U = 3 \times 500 V$
- Insulation material class: T40/B
- Overload: 1,5 x INenn 1 min / h
- Climatic category: DIN IEC 60068-1








## Technical data:

Туре	Rated voltage [V]	Rated current [A]	Inductance per branch [mH]	Capacity [mF]	Copper approx. [kg]	Weight approx. [kg]
CNW 961 / 2	Up to 3x 500V (50/60Hz)	2	33,4	0,11	1,4	5,2
CNW 961 / 4		4	16,7	0,34	1,65	5,5
CNW 961 / 6		6	11,0	0,50	3,0	5,8
CNW 961 / 10		10	6,60	1,10	4,5	9,1
CNW 961 / 16		16	4,20	1,10	5,0	13,0
CNW 961 / 24		24	2,83	1,50	6,5	17,3
CNW 961 / 30		30	2,20	2,20	12,0	37,0
CNW 961 / 37		37	1,64	2,20	12,5	38,0
CNW 961 / 48		48	1,41	3,30	16,2	42,0
CNW 961 / 60		60	0,91	4,70	17,0	62,0
Higher ratings upon request						

# Comparison between conventional Sinusoidal filters and Sinusoidal filter Plus







## REO (UK) Ltd.

Units 2-4 Callow Hill Road · Craven Arms Shropshire · SY7 8NT · UK Tel.: +44 (0)1588 673 411 Fax: +44 (0)1588 672 718

E-Mail: main@reo.co.uk Internet: www.reo.co.uk

Headquarter - Germany **REO INDUCTIVE COMPONENTS AG** Brühler Straße 100 · D-42657 Solingen Tel.: +49 (0)212 8804 0 · Fax: +49 (0)212 8804 188

E-Mail: info@reo.de Internet: www.reo.de

## China

REO Shanghai Inductive Components Co., Ltd No. 536 ShangFeng Road · Pudong, 201201 Shanghai · China Tel.: +86 (0)21 5858 0686 · Fax: +86 (0)21 5858 0289 E-Mail: info@reo.cn · Internet: www.reo.cn

#### France REO VARIAC S.A.R.L.

ZAC Du Clos aux Pois 1 · 6/8 rue de la Closerie-LISSES· F-91048 Evry Cédex Tel.: +33 (0)1 6911 1898 · Fax: +33 (0)1 6911 0918 E-Mail: reovariac@reo.fr · Internet: www.reo.fr

#### India

REO GPD INDUCTIVE COMPONENTS PVT. LTD 2/202 Luna Road · Village Luna · Taluka Padra Vadodara - 391440 · India Tel.: +91 (2662) 221723, +91 (265) 2396148 · Fax: +91 (265) 2396971 E-Mail: info@reogpd.com · Internet: www.reo-ag.in

#### Italy REO ITALIA S.r.l.

Via Treponti, 29 · I-25086 Rezzato (BS) Tel.: +39 030 279 3883 · Fax: +39 030 279 0600 E-Mail: info@reoitalia.it · Internet: www.reoitalia.it

## Poland

Poland REO CROMA Sp.zo.o ul. Pozaryskiego 28, bud 20 · PL-04-703 Warszawa Tel.: +48 (0)22 812 3066 · Fax: +48 (0)22 815 6906 E-Mail: croma@croma.com.pl · Internet: www.croma.com.pl

#### Spain REO ESPAÑA 2002 S.A.

C/Manuel Ventura i Campeny 21B · local 9 · E-08339 Vilassar de Dalt (Barcelona) Tel.: +34 937 509 994 · Fax: +34 937 509 995 E-Mail: info@reospain.com · Internet: www.reospain.com

## Switzerland

REO ELEKTRONIK AG Tel.: +41 (0)52 363 2820 · Fax: +41 (0)52 363 1241 E-Mail: info@reo.ch · Internet: www.reo.ch

#### Turke

Turkey REOTURKEY ELEKTRONIK San. ve Tic. Ltd. Şti. Halil Rifatpasa Mah. - Darülceze CD Perpa Tic Merkezi B Blok Kat 8 No:1095 - TR-34384 Sisli – Istanbul Tel.: +90 (0)212 2215 118 - Fax: +90 (0)212 2215 119 E-Mail: info@reo-turkey.com · Internet: www.reo-turkey.com

#### LISΔ REO-USA, Inc.

8450 E. 47th St · USA-Indianapolis, IN 46226 Tel.: +1 (317) 899 1395 · Fax: +1 (317) 899 1396 E-Mail: info@reo-usa.com · Internet: www.reo-usa.com